


10/549609

1/4

FIG. 1

TRANSMITTANCE UPON SINTERING AT 1100°C IN AIR




10/549609

2/4

FIG. 2

TRANSMITTANCE UPON SINTERING
AT 1100°C IN REDUCTION ATMOSPHERE



10/549609

3/4




FIG. 3

10/549609

4/4




FIG. 4